2021 Parks Report Card

Greg Stopka, Strategy and Innovation Manager

WHY GRADE OUR PARKS?



DEMONSTRATE PROGRESS



COMPARE PRESENT TO PAST AND FUTURE PERFORMANCE





DETERMINE **EFFECTIVENESS**

DIRECTION TO ALLOCATE RESOURCES

COMMUNICATE PRIORITIES



OUR GREATEST ASSET

 2019 Community Attitude and Interest Survey, 92% respondents visited a park or facility

HOW DO WE USE THIS INFO?

- Key metric in the Strategic Plan
- Guides CIP, plans, standards and procedures
- Staff meet annually to identify trends and actions for improvement






BOARD UPDATES

• The Board receives an annual update

2019-2021 Strategic Planat-a-Glance




INCLUSIVITY SUSTAINABILITY COMMUNITY ENGAGEMENT INNOVATION RESPONSIBLE LEADERSHIP INTEGRITY



| | Mission | | |
|---------|------------------------------|---------------------|--|
| | Vision | | |
| | Focus Areas | | |
| al h | Organizational Excellence | Staff Excellence | Quality Infrastructure Management |
| | Goals | | |
| e | <text><text></text></text> | <text></text> | <section-header><section-header></section-header></section-header> |

Values:


FEATURES EVALUATED




Athletic Fields



Seating Area



PARK DISTRICT of OAK PARK




FEATURES EVALUATED




Path and Sidewalks and Parking Lots






Drinking Fountains





OVERALL SCORES




The Park District defines the measurement as the average score of all parks, on a scale of 0 to 100, from the Park District's Park Report Card from the current year, indicating quality and maintenance of the park system. This measure is only for Park District park spaces. There is a separate report card for facilities (see Appendix B for park scores).



| What does the data say? Path and Sidewalks were down 2% (93 to 91). The biggest drop was at Maple (92 to 78). | 95 |
|---|----|
| What is driving the score(s)? The drop was due to fencing damage, tree weeds, natural debris, and large amounts of litter. | 90 |
| | 85 |

80






| What does the data say? Greenspaces were down 9% (97 to 88). The biggest drop was at Maple (100 to 79). | 95 |
|---|----|
| What is driving the score(s)? The drop was due to dead grass, empty tree pits, and a large amount of litter. | 90 |
| | 85 |

100






| What does the data say? Bathrooms were up 1% (93 to 94). The biggest increases were at Austin Gardens (75 to 97) and Fox (81 to 95). | 95 |
|---|----|
| What is driving the score(s)? Austin Gardens: The increase was due to the bathroom not being available in 2020. Fox: The increase was due to improvements in cleanliness and fixing broken equipment. | 90 |
| DI OREH EQUIPHIEIR. | 85 |

80






| 1 | | |
|---|-----|--------|
| | () | |
| | U | \cup |
| | U | U |


| What does the data say? Playgrounds were down 4% (98 to 94). The biggest drops were at Lindberg (98 to 86), Longfellow (98 to 89), and Barrie (99 to 90). | 95 |
|--|----|
| What is driving the score(s)? Lindberg: The drop was due to holes in the surface and debris on equipment. Longfellow: The drop was due to worn equipment and migrated sand on the splash | 90 |
| Barrie: The drop was due to migrated sand, paint and graffiti on seating, surface cracks, worn out equipment, missing bolts, and peeling paint. | 85 |





| | 100 |
|--|-----|
| What does the data say? Sitting Areas were down 6% (95 to 89). The biggest drops were seen at Lindberg (87 to 76), Field (99 to 78), Taylor (92 to 78), and Austin (98 to 86. | 95 |
| What is driving the score(s)? Lindberg: The drop was was due to paint and tape at the gazebo. Field: The drop was due to litter, tape, and tape at the second second | 90 |
| paint at the gazebo. <i>Taylor</i>: The drop was due to paint and tape at the gazebo. <i>Austin Gardens</i>: The drop was due to a broken seat/bench. | 85 |
| | |






| What does the data say? Athletic Spaces were down 4% (96 to 92). The biggest drops were seen at Taylor (96 to 86) and Carroll (98 to 92). | 95 |
|---|----|
| What is driving the score(s)? Taylor: The drop was was due to worn tennis court surfaces and net damage. Carroll: The drop was due to dead grass, | 90 |
| migrated sand, and stickers/paint. | 85 |

of OAK PARK


80



| What does the data say? Parking Lots were down 9% (95 to 86). The biggest drops were seen at Rehm (92 to 84) and RCRC (100 to 88). | 95 |
|---|----|
| What is driving the score(s)? <i>Rehm</i>: The drop was was due to faded lines and cracks. <i>RCRC</i>: The drop was due to faded lines and cracks. | 90 |
| cracks. | 85 |


80







APPENDIX A: EQUITY MAPS







| 20 | placed p two met around t the impa | 5 to repre arks on a rics to sec them. Acc acts of chr | sent childr graph base which par ording to N onic diseas | en and se d on dens ks have t IRPA, par ses, espec | of percent of niors in the sity (size of t he most you ks and recre |
|------|---|--|--|--|---|
| 17.5 | – – – such as o | children a | nd seniors. | i | i |
| | | | | | |
| | I | | 1 | 1 | 1 |
| 15 | | | | | · + |
| ТЭ | 11.5 | 12 | 12.5 | 13 | 13.5 |




APPENDIX B: PARKS SCORES



Major Issues **Athletic Spaces:**

Soccer Field: Brown patches, holes in the field, and poor trimming around trees and plaques

Playgrounds: Trimmed branches left behind and really tall weeds by the fence



What does the data say?



Andersen Park

• Andersen Park saw a 1% increase (93 to 94) driven by a 3% improvement in its Path and Sidewalks and Bathrooms.

Minor Issues **Athletic Spaces:**

• *Soccer Field*: Empty tree pit, and bare spots

Bathrooms:Toilet caulk separating, dirty vent, and grime on wall

Path and Sidewalks:

- Exterior: Missing dome cap on fence, cracks, weeds plastic rings on fence, dirty signage, and etching on sidewalk
- Interior: Uneven cracks

Playgrounds: Broken fence posts, sticker residue, and woodchips on playground

Sitting Areas: Level cracks, gunk on sidewalk and paint on seating


Major Issues **Greenspaces:** Major bare spots from theater

Path and Sidewalks:

- Exterior: Graffiti and image on fence; footprints in cement
- *Interior*: Paint/graffiti on \bullet bench, smiling face on sign

Sitting Areas: Broken,

crumbling seat/leg and grime on table



What does the data say? • Austin Gardens received the same score (92) in 2021 and 2020.



Minor Issues **Bathrooms**: Missing tiles and tape and grime

Greenspaces: Litter

Path and Sidewalks:

- Exterior: Poop on fence, wood damage on fence
- Gravel: Empty planters and weeds in plant bed, sticker on sign
- *Interior*: Empty tree pit, cracks, litter, and dirty sign
- *Dirt*: Limbs in the plant bed and litter

Sitting Areas: Weeds

Major Issues **Athletic Spaces:**

- Sledding Hill: Graffiti on pad/fence, sticker on post, railing damaged and rusty, and pad torn
- Pickle Ball Court: Litter, leaf debris, cracks, and worn surface
- Basketball Court: Worn surface
- Diamond: Sand in dugout and grime on storage container


Bathrooms: Dirty toilet seat, grime on wall, and stickers

Path and Sidewalks:

Exterior: Dead trees, \bullet damage to cement around rail/stone risers missing, desired lines, bare spots, and large cracks

Sitting Areas: Tall weeds

Playgrounds: Migrated sand, paint/graffiti on seating, surface cracks, worn out equipment, missing bolts, and peeling paint



What does the data say?

• Barrie is down 4% (96 to 92) driven by a drop in Path and Sidewalks (93 to 87),



Playgrounds (99 to 90), Athletic Spaces (96 to 91), and Sitting Areas (95 to 88).

Minor Issues **Athletic Spaces:**

- Sledding Hill: Fence post rusty and missing caps, and caution tape
- Diamond: Paint on bench
- Soccer Field: Bare spots and litter

Bathrooms: Mold around sink and grime on floor

Path and Sidewalks:

- Exterior: Sticker residue on board, spray paint on sign, and bird poop on bench
- *Interior*: Weeds, migrated side, and sticky substance on bench

Playgrounds: Bird poop on fence


Sitting Areas: Worn bench, big puddle by door, and etching on bench

Major Issues Path and Sidewalks: Migrated sand on sidewalk and large amount of grime through out

Greenspaces: Behind the school, large amount of algae, siding is very long, dead grass, and downed fencing and rust. By the community center, grass isn't growing or dead and large weeds

Athletic Spaces:

Diamond: Dead grass



Year *Carroll was under construction in 2019*

What does the data say?

• Carroll is down 5% (99 to 94) driven by a drop in Athletic Spaces (98 to 92), Greenspaces (98 to 87), and Path and Sidewalks (99 to 94).



Carroll Park

Minor Issues Path and Sidewalks: peeling fence, weeds in plant bed, level cracks, and litter

Sitting Areas:

- *Flagpole:* Grime on garbage can, markers, and large crack in sculpture,
- *Rocks*: Bare spots and sculpture


Bathrooms: Grime/dirt on soap dispenser

Athletic Spaces:

Diamond: Migrated sand on bleachers and floor and blue paint/stickers on fence

Major Issues Path and Sidewalks:

- *Pond:* Sticker residue and graffiti
- *Exterior:* Rust forming on fence, damage to brick
- holding fence together *Main: S*idewalk, bricks chipping, and back stairs concrete separating



What does the data say?

and Path and Sidewalks (93 to 88).



Cheney Mansion


• Cheney is down 5% (97 to 92) driven by a drop in Greenspaces (100 to 96)

Minor Issues Path and Sidewalks:

Exterior: Concrete post damage, gap on sidewalk, and bird poop on signage

Greenspaces: Bare spot and ground cover growth under bench and litter

<u>Major Issues</u> **Playgrounds:** Over grown bushes on walkway



What does the data say?

the Parks Report Card.



Conservatory

Minor Issues **Playgrounds:** Large weeds in the landscaping

Sitting Areas: Tape residue on fence

• Conservatory received a 99. This is the first year Conservatory was included in

Major Issues **Athletic Spaces:**


- Diamond: Large amount of paint peeling on fence, and etching (bleachers), and graffiti on storage container
- Tennis: Level cracks and tall weeds

Path and Sidewalks:

Main: Large amount of stickiness on garbage can

Playgrounds: grime on surface and woodchips/ leaves on playground

Sitting Areas: Litter



What does the data say? • Euclid Square received the same score (96) in 2021 and 2020.



Euclid Square

Year

Minor Issues **Athletic Spaces:**

Tennis: Litter, and migrated pine needs/acorns and bird poop


Path and Sidewalks:

- *Exterior:* Empty tree pit, litter, and bird poop and etching on bench
- Main: Worn or bare spots and light post graffiti

Playgrounds: Litter and a bunch of stickers on equipment

Sitting Areas: Pine needles and leaves

Major Issues **Athletic Spaces:** Bocce Ball: Divots in surface Diamond: Migrated sand ${\color{black}\bullet}$ and graffiti on fence and storage container Path and Sidewalks: Main: Paint on sidewalk and graffiti on storage container **Playgrounds:** Grime on swing set and graffiti on bench Sitting Areas: Litter and grime on tables



What does the data say?

a drop in Sitting Areas (99 to 78).



Field Park

• Field Park is down 4% (96 to 92) driven by

Minor Issues **Athletic Spaces:**

- Diamonds: Fence buckling/peeling, litter, and equipment out
- Field: Worn/dry spots by net

Bathrooms: Caulking is separating and grime on vents

Drinking Fountains: Algae in dog bowl

Path and Sidewalks:

- *Exterior*: Litter and wiring in grass
- Main: Uneven sidewalk, dirty signage

Greenspaces: Tree root tripping hazard and worn/bare spots

Playgrounds: Chipped paint on two locations and gunk on garbage can

Sitting Areas: Tape on posts and paint on table

Major Issues **Athletic Spaces:**

Diamond: Trash and sand by the bench

Bathrooms: Rust and grime on soap dispenser

Drinking Fountains: Gunk in drain

Grade


Path and Sidewalks:

Main: Major damage to staircase infrastructure, footprint in cement, stickers on sign, and etching on staircase and bench, uneven sidewalk, bare spots, migrated debris, large branch by the sidewalk, and grime and bird poop on bench

Playgrounds:

- Main: gate looks rusty and migrated sand
- Splash Pad: Large amount of litter

Sitting Areas: Weeds in pavers, migrated woodchips, and grime and paint on tables



What does the data say?

drop in Sitting Areas (97 to 90), Sidewalks (90 to 84).



Year

• Fox Park is down 1% (93 to 92) driven by a Playgrounds (100 to 92), and Path and

Minor Issues **Athletic Spaces:**

Diamond: Marker on bench

Bathrooms: Mold and grime around urinal and tile

Drinking Fountains: Purpose paint and sticker residue

Path and Sidewalks:

Main: Bench arm and fence post peeling

Playgrounds:

Main: Some equipment is looking worn, sticker residue, and weeds by benches

Sitting Areas: Trash in plant beds

Major Issues **Athletic Spaces:**

- Diamonds: Bases, pad, and block out
- Fields: Many worn/bare/dry spots
- *Tennis:* Very worn/cracks in surface

Bathrooms: Graffiti and bee bee shot on/in mirror, hole, messy tiles, chips in mirror, and door peeling


Greenspaces: Hard to walk through the path

Path and Sidewalks:

- *Main*: Graffiti/etching by flag pole, benches
- Exterior: Graffiti and etching on benches, major cracks, exposed post footer, and dead grass

Playgrounds: Holes in surface, and dirty signage and equipment

Sitting Areas: Paint and tape



Grade

What does the data say?



Lindberg Park 2020 2021 2019

Year

Lindberg Park is down 6% (95 to 89) driven by a drop in Sitting Areas (87 to 76), Playgrounds (98 to 86), Path and Sidewalks (94 to 88), and Greenspaces (99 to 94).

Minor Issues **Athletic Spaces:**

- Diamonds: Graffiti on fence and paint on bleacher, plastic rings and litter, gunk on garbage can and bleachers, worn storage bin, worn spots in field, weeds in bleacher, and rubber noddle hanging from cage top
- *Tennis*: Dirty trash can and signs

Bathrooms: Pink marker on walls, wet toilet paper and dirty door

Drinking Fountains: Bird poop

Greenspaces: Weeds

Path and Sidewalks:

- Main: Food residue and seating grime, Empty tree pit and chipping flag pole base
- Exterior: Grime and tar substance by bench, pine needles, limbs, and other debris

Playgrounds: Peeling fence

Sitting Areas: Gunk on table

Major Issues **Athletic Spaces:** Diamond: Migrated sand 100 *Tennis*: Lines fading and major cracks Path and Sidewalks: 95 Main: Etching and tire marks, mulch out of beds, grime/poop on sign, migrated sand, uneven Grade sidewalk, and major bare 90 spots 88 **Playgrounds:** Main: Bird poop and grime 85 on fences, migrated sand, worn equipment, and surface damage Splash Pad: Migrated sand 80

Sitting Areas:

Court: Litter


> What does the data say? • Longfellow Park is down 1% (95 to 94) driven by a drop in Sitting Areas (99 to 94), Playgrounds (98 to 89), and Athletic

Spaces (99 to 94).

2018



Longfellow Park



Year

Minor Issues **Athletic Spaces:**

- Diamond: Litter
- Tennis: Plastic rings and branches
- Field: Weeds around tree
- Basketball: Bleacher end caps missing, litter, leaves, grime by bench, and bird poop on court

Bathrooms: Grime on tile

Playgrounds:

Main: Empty tree pit

Sitting Areas:

- *Center:* Grime on table, worn/bare spots, peeling arm rest, cracks on bench, grate bent, and missing cement sections
- *Court*: Bird poop on benches

Major Issues **Athletic Spaces:**

- Diamonds: Debris, bird poop/grime on bench/bleacher, plank loose, and seat is bent
- *Tennis*: Burnt spots/cracks on court

Bathrooms: Blood on wall from drug use and grime

Path and Sidewalks:


- Main: Debris staining sidewalk, charcoal substance on bench, many cracks, hole in garbage can, and large amount of tree weeds
- Exterior: Debris staining ${\color{black}\bullet}$ sidewalk, fencing damage, litter, and clothing hanging on fence

Greenspaces: Dead trees and grass, empty tree pit, and litter

Playgrounds: Shoe marks on slide and migrated mulch, and stickers

Sitting Areas: Litter,

tape, food trash, and person sleeping on ground



What does the data say?

and Greenspaces (100 to 79).



Maple Park 94-2020 2021

Minor Issues **Athletic Spaces:**

- *Diamonds*: Cap is peeling
- *Tennis:* Litter

Bathrooms: Elastic strap for drug use

Playgrounds: Border bed weeds no plantings

Sitting Areas: Level cracks and marker on table

Year


Maple Park is down 7% (94 to 87) driven by a drop in Path and Sidewalks (92 to 78)

<u>Major Issues</u> Path and Sidewalks:

- Interior: Tree trunk down
- Exterior: Moderate curb damage, moderate cracks
- Gravel: Low gravel, ${\color{black}\bullet}$ exposed fabric, debris, and broken tree trunk

Greenspaces:

South: Plaque not set properly



The greenspace behind Pleasant Home at Mills Park was under construction in 2021

What does the data say?

a drop in Greenspaces (99 to 88).



Mills Park

Year

Mills Park is down 2% (92 to 90) driven by

Minor Issues Path and Sidewalks:


- *Interior:* Minor cracking of bench, empty plant bed, paint on rock
- *Exterior*: Litter, bird poop \bullet on fence, foot prints in cement, and exposed wiring on light post
- Gravel: Minor cracking of bench, and weeds around trees

Greenspaces:

- Main: Tree weeds, dead tree stump, large divots
- *South:* Exposed roots, bare spots
- **Pleasant Home: Weeds** around trees

<u>Major Issues</u> Path and Sidewalks:

- Main: Sign is down by fitness equipment and large amount of dead grass
- *Exterior*: Bent fence post lacksquarein two spots and dirty all over the fence in multiple spots



What does the data say?

• Randolph Park is down 2% (96 to 94) driven by a drop in Path and Sidewalks (94 to 89).



Minor Issues **Playgrounds:**

- *Tot Lot:* Limbs
- *Workout Equipment:* Grime \bullet

Major Issues **Athletic Spaces:**

- *Field*: Large amount of geese poop everywhere
- *Exterior*: Bent fence post in \bullet two spots and dirty all over the fence in multiple spots


Path and Sidewalks:

- Exterior: Overgrown ground cover and dead branches
- Main: Large weeds in beds, lacksquarepaint on sidewalk/post, and etching on bench

Grade

Parking Lots: Faded lines

Greenspaces: Empty plant bed



What does the data say?

increase in Playground (86 to 99).





Year

• Rehm Park is up 4% (89 to 93) driven by an

Minor Issues **Athletic Spaces:**

- *Field*: Empty tree pit
- *Tennis:* Leaves
- *Volleyball*: Litter

Path and Sidewalks:

- Exterior: Bike rack rust
- Main: Bird poop on benches and migrated sand

Parking Lots: Holes, cracks, and worm/bare spots

Playgrounds: Leaves

Sitting Areas: Grime on trash can lid


Major Issues **Athletic Spaces:**

- *Diamond*: Really tall weeds and litter
- *Fields*: Litter along south ${\color{black}\bullet}$ side

Bathrooms: Marker graffiti

Parking Lots: Faded lines

Sitting Areas: Large amount of litter



What does the data say? • Ridgeland Common had the same score (95) in 2021 and 2020.



Year

Minor Issues **Athletic Spaces:**

- *Diamond*: Paint/gunk on bleacher and surface
- Field: Wooden base \bullet boards broken and splintering

Path and Sidewalks: Banner worn and frayed, bare spots, cracks, grime on garbage can, graffiti on bike stand, and sticker residue on post

Parking Lots: Cracks

Sitting Areas: Weeds

Major Issues **Athletic Spaces:**

Tennis: Major cracks forming

Path and Sidewalks:

- Exterior: Trimmed branches left behind
- Main: Sticker residue on sign by playground, graffiti on sign, and paint on block and garbage can

Bathrooms: Dirty vents, excessive wear



What does the data say?

• Scoville Park had the same score (94) in 2021 and 2020.





Minor Issues **Athletic Spaces:**

Tennis: Small hole in net

Path and Sidewalks:

- *Exterior*: Empty tree pit, worn/bare spots, litter, and debris
- Main: Bird poop on bench

Bathrooms: Slightly worn corners, caulk issues, mold by sink, glue residue, and inconsistent signage

Drinking Fountains: Dirty surface

Passive Greenspaces: Leaf debris and litter

Playgrounds: Equipment peeling, migrated sand outside the box, low sand level, and paint on bench.


Sitting Areas: Trash can chewed and flap not secure, weeds, some blocks out in plant bed, and flagpole rust

<u>Major Issues</u> **Athletic Spaces:**

- Basketball: Shattered backboard and cracks and worn spots
- Diamond: Large amount of ${\color{black}\bullet}$ weeds in stone area
- *Skateboard*: Litter, lacksquareand graffiti on bench and stickers on house, table, surface, and benches

Path and Sidewalks:

Main: Damage by stairs/ ${\color{black}\bullet}$ weather damage



Stevenson Park was under construction in 2019

What does the data say?

2021 and 2020.



• Stevenson Park had the same score (96) in

Minor Issues **Athletic Spaces:**

- Basketball: Slight hole in the net, littler, pine needle debris, and sticker on sign
- Diamond: Bent bleacher seat, littler, and brown grass patches
- *Field*: Worn/bare/burnt
- Skateboard: Fence peeling, planters not managed, and grime on table

Drinking Fountains: Stickers

Path and Sidewalks:

- *Exterior*: Tall weeds, litter, and level cracks
- Main: Litter, grime on trash can, and migrated woodchips

Sitting Areas: Litter and grime on ping pong table

<u>Major Issues</u> **Athletic Spaces:**

- *Field*: Line of bare/brown spots and some by the nets
- *Tennis*: Net torn, major ${\color{black}\bullet}$ cracks/worn spots, and tall weeds

Bathrooms:

- *East*: Mirror unusable, wall worn/damaged
- West: Paint smears and dirt on window, mirror unusable, wood pieces torn, and holes in wall

Greenspaces: Brown patches and grass clippings dumped


Playgrounds: Large amount of tree weeds, major desired line toward gazebo

Path and Sidewalks:

- Main: Large tree weeds
- *Exterior*: Empty tree pits, one tree trunk, limbs left by tree, grass clippings on sidewalk

Sitting Areas:

Gazebo: Dirt and paint on tables and ground



What does the data say?

89).



Minor Issues **Athletic Spaces:**

- *Tennis*: Scratches by handle
- Field: Litter

Bathrooms:

East: Glue residue on door, wet toilet paper, scratches on window, and sticker residue

Drinking Fountains: Dirty surface

Path and Sidewalks:

- *Exterior*: Litter and gunk on garbage can
- Main: Worn spots and graffiti by/on bleacher, cracks near wetlands, and equipment out

Greenspaces: Trash and evidence of fire crackers

Playgrounds: Plastic rings, migrated woodchips, and sticker residue

Sitting Areas:


- *Gazebo*: Trash can hole, gunk, cracks in table and surface
- Grills: Edging material



• Taylor Park is down 4% (92 to 88), driven by an drop in Athletic Spaces (96 to 86), Sitting Areas (92 to 78), and Playgrounds (97 to

<u>Major Issues</u> Path and Sidewalks:

- Main: Buckling fence panels along North Side and a large amount of dead grass Exterior: Tall weeds



Wenonah Park was under construction in 2019

What does the data say?

• Wenonah Park is down 6% (96 to 90), to 86).



driven by an drop in Path and Sidewalks (93)

Minor Issues Path and Sidewalks:

- Exterior: Bird poop and \bullet rust on fence and torn sticker on bike rack
- Main: Tall weeds

Playgrounds: Level cracks and dirt on seating legs